INFORMATION REPORT INFORMATION REPORT

CENTRAL INTELLIGENCE AGENCY

This material contains information offecting the National Defense of the United States within the meaning of the Espionage Laws. Title 18, U.S.C. Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

COUNTRY	Bulgaria	REPORT	
SUBJECT	The Sofia-Lovech-Zlatitsa Junction	DATE DISTR.	16 March 1955
	to Zlatitsa Road	NO. OF PAGES	y
DATE OF INFO.		REQUIREMENT NO.	RD
PLACE ACQUIRED	This is UNEVALU	REFERENCES JATED Information	
DATE ACQUIRED			

- 1. The first two kilometers of the road from the Sofia-Lovech-Zlatitsa junction (N42-55, E23-54) to Zlatitsa (N42-43, E24-08) has the following characteristics:
 - a. Width, four to five meters;

25X1

- o. Surface, crushed stone and earth in fair condition, some potholes;
- c. Shoulder, one meter; flush; earth;
- d. Straight and level; and
- e. Flat, open fields on both sides.
- 2. Two to three (Pravets; N42-54, E23-55) kilometers:
 - a. Width, five meters;
 - b. Surface, crushed stone and earth in fair condition, some potholes;
 - c. Shoulder, two meters on both sides; flush; earth;
- 3. Three to ten kilometers:
 - a. Width, four to five meters;
 - b. Surface, crushed stone and earth in fair condition;
 - c. Shoulder, one meter both sides; flush; earth;
 - d. Curving and climbing gently; no sharp turns; and
 - e. Narrow wooded valley.
- 4. 10 to 14 kilometers:
 - a. Width, four to five meters;
 - b. Surface, crushed stone and earth in fair condition;
 - c. Shoulder, one meter both sides; flush; earth;
 - d. Road descends, levels at 12 kilometers; and
 - e. Wide, open valley; fields and clumps of trees alternating; vehicles can leave road at some points.

S-E-C-R-E-T

25X1

STATE	х	ARMY	ж	NAVY	ж	AIR	x	FBI	AEC	ORR. @	x	
		<u> </u>	h				(Note	: Washin	gton distribution	indicated by "X"; Fig	eld distribution by "#	".)

INFORMATION REPORT


INFORMATION REPORT

S-E-C-R-E-T

	- 2 -
:	L4 to 17 kilometers:
ł	 Width, five meters; Level road, under repair; new crushed stone foundation (width, five meters) throughout; earth surface not yet laid; and Open valley; flat fields both sides, no cover.
	.7 to 19 (Etropole; N42-50, E24-00) kilometers:
e t	 Width, five meters; Surface, crushed stone and earth, fair condition; Shoulder, one to two meters on both sides; flush;
נ	9 to 24 kilometers:
b d	 Width, four to five meters; Surface, crushed stone and earth, fair condition; Shoulder, one meter on both sides; flush; Straight and level, climbing slightly after 22 kilometers; and Flat fields on both sides; narrow valley after 22 kilometers.
2	4 to 34 kilometers:
b d e	 Width, four to five meters; Surface, crushed stone and earth; poor condition; abutments in good repair; Shoulder, one meter on both sides; flush; Climbs steadily in series of curves to top of pass at 34 kilometers; Mountainous; heavily wooded; vehicles cannot leave road; and Heavy snow probable in winter; road normally remains open throughout winter due to regular use by trucks from saw-mills and logging camps in the area.
3	4 to 42 kilometers:
b c d	 Width, four to five meters; Surface, crushed stone and earth; in fair condition; Shoulders, one meter on both sides; flush; earth; Descends in a series of sharp hairpin curves; Mountainous; wooded; and Used by heavy trucks.
14	2 to 47 kilometers:
a, b, c, d,	Surface, crushed stone and earth; in fair condition; Shoulders, one meter on both sides; flush; earth; Straight and level; crosses single-track railway line at 46 kilometers; and Narrow gorge between 42 and 44 kilometers; 44-47 kilometers, flat, open coun
	S-E-C-R-E-T
	5 5-0-1-B-1

S-E-C-R-E-T 25X1

APPENDIX



SCALE: 1:250,000

S-R-C-R-R-T

